






G1
2x




G



O









F = 4x







L = 8x (A= 520mm)


L = 10x (A= 700mm)









1




2




3





A	520	700
L1	497	677






4






5





6a






6b



7a



7b



8

